EXHIBIT B-6

COMPANY: State Farm

CLAIM # 53-135N-169

INSURED: Silvana Espinoza ADDRESS: 609 Tara Dr. Pharr, Texas 78577

AWARD

Dwelling	\$20,372.51	
Other Structures	NA.	
	NESHINA NESHINAN NESHI N	
UAL CASH VALUE	\$18,184.06	
AL AMOUNT OF LOS	SS \$20,372.51	_
2. Less any previous	provisions and deductible payments per this claim be addressed by others	
ess our hands this 26th	day of January , 2016.	

Insured:

Silvana Espinoza

Property:

609 Tara Dr.

Pharr, TX 78577

Estimator:

Cecil Parker

Claim Number: 53-135N-169

Policy Number: 83-BS-R741-6

Type of Loss: ---

Date of Loss:

3/29/2012

Date Received:

Date Inspected: 12/27/2015

Date Entered:

1/25/2016 6:12 PM

Price List:

TXMC8X_JAN16

Restoration/Service/Remodel

Estimate:

53-135N-169

53-135N-169 Exterior Damage

Roof

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
Remove Laminated - comp. shingle rfg. w/ felt	- 32.30 SQ	49.27	0.00	318.28	1,909.70	(0.00)	1,909.70
Remove Additional charge for steep roof - 7/12 to 9/12 slope	32.30 SQ	8.60	0.00	55.56	333.34	(0.00)	333.34
3. Laminated - comp. shingle rfg w/ felt	37.33 SQ	178.97	308.40	1,397.88	8,387.23	(1,336.19)	7,051.04
4. Additional charge for steep roof - 7/12 to 9/12 slope	37.33 SQ	26.38	0.00	196.96	1,181.73	(0.00)	1,181.73
5. Asphalt starter - universal starter course	286.00 LF	1.31	11.56	77.26	463.48	(74.93)	388.55
R&R Drip edge	286.00 LF	1.68	14.86	99.08	594.42	(84.08)	510.34
7. R&R Valley metal	125.00 LF	3.88	16.91	100.40	602.31	(87.75)	514.56
8. (Install) Ridge cap - composition shingles	268.00 LF	1.94	0.00	103.98	623.90	(103.98)	519.92
9. R&R Flashing - pipe jack	5.00 EA	29.65	3.55	30.38	182.18	(25.31)	156.87
10. R&R Roof vent - turtle type - Metal	1.00 EA	43.09	1.24	8.86	53.19	(7.51)	45.68
11. R&R Continuous ridge vent - shingle- over style	28.00 LF	6.44	6.84	37.44	224.60	(33.15)	191.45
 Digital satellite system - Detach & reset 	1.00 EA	22.30	0.00	4.46	26.76	(0.00)	26.76
13. Digital satellite system - alignment and calibration only	1.00 EA	66.89	0.00	13.38	80.27	(0.00)	80.27
Totals: Roof			363.36	2,443.92	14,663.11	1,752.90	12,910.21

Exterior

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
14. Reglaze double-pane thermal window unit, 10 - 16 sf - 1 on front elev / 1 on right elev.*	2.00 EA	226.74	28.24	96.34	578.06	(90.70)	487.36
 Add on for grid (double or triple pane windows) 	15.00 SF	2.35	2.91	7.64	45.80	(0.00)	45.80
16. Add on for "Low E" glass	15.00 SF	1.71	2.12	5.56	33.33	(0.00)	33.33
Totals: Exterior			33.27	109.54	657.19	90.70	566.49

Total: Exterior Damage 396.63 2,553.46 15,320.30 1,843.60 13,476.70

Interior Damage

Entry/Foyer

Height: 12'

835.44 SF Walls 1110.85 SF Walls & Ceiling 30.60 SY Flooring 76.33 LF Ceil. Perimeter 275.41 SF Ceiling 275.41 SF Floor 64.25 LF Floor Perimeter

Missing Wall - Goes to Floor 3' X 6' 8" 3' X 6' 8" 3' X 6' 8" 3' 1" X 6' 8" Opens into HALL
Opens into LIVING_ROOM
Opens into LIVING_ROOM
Opens into KITCHEN

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
17. R&R 1/2" drywall - hung, taped, floated, ready for paint	32.00 SF	1.66	1.08	10.84	65.04	(8.96)	56.08
18. R&R Blown-in insulation - 12" depth - R30	32.00 SF	1.37	1.48	9.06	54.38	(4.93)	49.45
19. Apply plant-based anti-microbial agent	32.00 SF	0.18	0.69	1.18	7.63	(0.00)	7.63
20. Texture drywall - light hand texture	32.00 SF	0.35	0.11	2.26	13.57	(2.24)	11.33
21. Seal/prime then paint the ceiling (2 coats)	275.41 SF	0.70	3.41	39.24	235.44	(38.56)	196.88
22. Paint the walls - two coats	835.44 SF	0.68	13.10	116.24	697.44	(113.62)	583.82
23. Content Manipulation charge - per hour	1,00 HR	26.13	0.00	5.22	31.35	(0.00)	31.35
 Floor protection - self-adhesive plastic film 	275,41 SF	0.47	2,95	26.48	158.87	(0.00)	158.87
 Detach & Reset Heat/AC register - Mechanically attached 	2.00 EA	8.83	0.00	3,54	21.20	(0.00)	21.20
 Detach & Reset Recessed light fixture trim only 	2.00 EA	2.02	0.00	0.80	4.84	(0.00)	4.84
27. Detach & Reset Hanging light fixture	2.00 EA	34.91	0.00	13.96	83.78	(0.00)	83.78
 Window blind - horizontal or vertical - Detach & reset 	4.00 EA	22.39	0.00	17.92	107.48	(0.00)	107.48
29. Detach & Reset Smoke detector	1.00 EA	33.82	0.00	6.76	40.58	(0.00)	40,58
30. Detach & Reset Door chime*	1.00 EA	33.01	0.00	6.60	39.61	(0.00)	39.61
31. Detach & Reset Thermostat - electric heat	1.00 EA	29.48	0.00	5.90	35.38	(0.00)	35.38
32. Clean floor - tile	275.41 SF	0.42	12.71	23.36	151.74	(0.00)	151.74
Totals: Entry/Foyer			35.53	289.36	1,748.33	168.31	1,580.02

38. Clean floor - tile

Totals: Living Room

53-135N-169

3: 118	Room					1	Height: 12'	
82 1	594.8	9 SF Walls		208.00 SF Ceiling				
en Living Room	802.8	9 SF Walls & Co	eiling	208.00 SF Floor				
E Living Room	23.11 SY Flooring			42.83 LF Floor Perimeter				
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	58.00 LF Ceil. Perimeter							
Missing Wall - Goes to Floor	9' 2" X 6' 8"			Opens into KITCHEN				
Missing Wall - Goes to Floor	3' X 6' 8"			Opens into ENTRY_FOYER				
Missing Wall - Goes to Floor	3' 2	K 6' 8"	Opens into ENTRY_FOYER			FOYER		
DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV	
33. Mask and prep for paint - tape only (per LF)	58.00 LF	0.41	0.19	4.80	28.77	(0.00)	28.77	
34. Paint the walls - two coats	594.89 SF	0.68	9.32	82.76	496.61	(80.91)	415.70	
 Content Manipulation charge - per hour 	2.00 HR	26.13	0.00	10.46	62.72	(0.00)	62.72	
36. Floor protection - self-adhesive plastic film	208.00 SF	0.47	2.23	20.00	119.99	(0.00)	119.99	
 Window blind - horizontal or vertical - Detach & reset 	3.00 EA	22.39	0.00	13.44	80.61	(0.00)	80.61	

0.42

9.60

21.34

17.66

149.12

114.62

903.32

(0.00)

80.91

1/26/2016

114.62

822.41


Page: 4

208.00 SF

2' 4'-3'-2' 7' Kite	hen						Height: 12'	
	584.33	SF Walls		150.81 SF Ceiling				
Kilchen	735.14	SF Walls & Co	eiling	150.81 SF Floor				
50 Liv	16.76 SY Flooring			43.25 LF Floor Perimeter				
5 5 7 2.4*	55.50	LF Ceil. Perim						
Missing Wall - Goes to Floor	3' 1	" X 6' 8"		Opens into ENTRY_FOYER				
Missing Wall - Goes to Floor	9' 2" X 6' 8"				Opens into LIVING_ROOM			
Subr)					Height: 8'		
3'5"	113.26	SF Walls			12.51 SF	Ceiling		
*	125.77	SF Walls & Ce	iling	12.51 SF Floor				
	1.39	SY Flooring			14.16 LF	Floor Perimete	oor Perimeter	
9"1	14.16	LF Ceil. Perim	eter					
DESCRIPTION	QUANTITY 1	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV	
39. Mask and prep for paint - tape only (per LF)	69.66 LF	0.41	0.23	5.76	34.55	(0.00)	34.55	

CONTINUED - Kitchen

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
40. Paint part of the walls - two coats	523.19 SF	0.68	8.20	72.80	436.77	(71.15)	365.62
41. Content Manipulation charge - per hour	2.00 HR	26.13	0.00	10.46	62.72	(0.00)	62.72
42. Floor protection - self-adhesive plastic film	163.32 SF	0.47	1.75	15.72	94.23	(0.00)	94.23
43. Window blind - horizontal or vertical - Detach & reset	3.00 EA	22.39	0.00	13.44	80.61	(0.00)	80.61
44. Remove Security system - key pad	1.00 EA	1.73	0.00	0.34	2.07	(0.00)	2.07
45. (Install) Security system - key pad	1.00 EA	70.41	0.00	14.08	84.49	(0.00)	84.49
46. Clean floor - tile	163.32 SF	0.42	7.52	13.86	89.97	(0.00)	89.97
Totals: Kitchen			17.70	146.46	885.41	71.15	814.26



Hall Height: 8'

240.00 SF Walls 282.25 SF Walls & Ceiling

4.69 SY Flooring 32.50 LF Ceil. Perimeter 42.25 SF Ceiling

29.50 LF Floor Perimeter

42.25 SF Floor

Missing Wall - Goes to Floor

3' X 6' 8"

Opens into ENTRY_FOYER

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
47. Mask and prep for paint - tape only (per LF)	32.50 LF	0.41	0.11	2.68	16.12	(0.00)	16.12
48. Paint part of the walls - two coats	180.00 SF	0.68	2.82	25.04	150.26	(24.48)	125.78
49. Content Manipulation charge - per hour	2.00 HR	26.13	0.00	10.46	62.72	(0.00)	62.72
50. Floor protection - self-adhesive plastic film	42.25 SF	0.47	0.45	4.08	24.39	(0.00)	24.39
51. Detach & Reset Smoke detector	1.00 EA	33.82	0.00	6.76	40.58	(0.00)	40.58
52. Clean floor - tile	42.25 SF	0.42	1.95	3.60	23.30	(0.00)	23.30
Totals: Hall			5.33	52.62	317.37	24.48	292.89
Total: Interior Damage			79.90	637.56	3,854.43	344.85	3,509.58

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
53. Residential Supervision / Project Management - per hour	4.00 HR	50.30	0.00	40.24	241.44	(0.00)	241.44
54. Haul debris - per pickup truck load - including dump fees	1.00 EA	98.18	0.00	19.64	117.82	(0.00)	117.82
55. Temporary toilet (per month)	1.00 MO	132.01	0.00	26.40	158.41	(0.00)	158.41
56. Taxes, insurance, permits & fees (Bid item)	1.00 EA	150.00	0.00	30.00	180.00	(0.00)	180.00
57. Scaffold - per section (per week) - 4 sections / 2 weeks*	2.00 WK	48.00	0.00	19.20	115.20	(0.00)	115.20
58. Scaffolding Setup & Take down - per hour and moving room / room.*	2.00 HR	26.13	0.00	10.46	62.72	(0.00)	62.72
Totals: General			0.00	145.94	875.59	0.00	875.59

Labor Minimums Applied

DESCRIPTION	QUANTITY U	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
59. Drywall labor minimum*	1.00 EA	179.60	0.00	35.92	215.52	(0.00)	215.52
60. Window labor minimum*	1.00 EA	28.11	0.00	5.62	33.73	(0.00)	33.73
61. Insulation labor minimum*	1.00 EA	60.78	0.00	12.16	72.94	(0.00)	72.94
Totals: Labor Minimums Applied			0.00	53.70	322.19	0.00	322.19
Line Item Totals: 53-135N-169			476.53	3,390.66	20,372.51	2,188.45	18,184.06

Grand Total Areas:

971.09	SF Walls SF Floor SF Long Wall	107.90	SF Ceiling SY Flooring SF Short Wall	289.82	SF Walls and Ceiling LF Floor Perimeter LF Ceil. Perimeter
F 5	Floor Area Exterior Wall Area		Total Area Exterior Perimeter of Walls	3,134.59	Interior Wall Area
	Surface Area Total Ridge Length		Number of Squares Total Hip Length	0.00	Total Perimeter Length

53-135N-169 1/26/2016 Page: 6

Summary for Dwelling

Line Item Total	16,505.32
Material Sales Tax	444.06
Cleaning Mtl Tax	2.95
Subtotal	16,952.33
Overhead	1,695.33
Profit	1,695.33
Cleaning Sales Tax	29.52
Replacement Cost Value	\$20,372.51
Less Depreciation	(2,188.45)
Actual Cash Value	\$18,184.06
Net Claim	\$18,184.06
Total Recoverable Depreciation	2,188.45
Net Claim if Depreciation is Recovered	\$20,372.51

Cecil Parker

53-135N-169 1/26/2016 Page: 7